	Type	Hits	Search Text		
1	IS&R	2275	("33/503,1m,504,549,551,553,554,555").CCLS		
2	BRS	31	(("33/503,1m,504,549,551,553,554,555").CCL S.) and @pd>20000701		
3	BRS	22456	(("33/503,1m,504,549,551,553,554,555").CCL S.) and pallet changer		
4	BRS	0	(("33/503,1m,504,549,551,553,554,555").CCL S.) and pallet adj changer		
5	BRS	619	(("33/503,1m,504,549,551,553,554,555").CCL S.) and plate		
6	BRS	14	coordinate adj measuring and rotating adj table		
7	BRS	10	(("33/503,1m,504,549,551,553,554,555").CCL S.) and changer		
8	BRS	547	pallet and changer		
9	BRS	201	pallet adj changer and tool		
10	BRS	1	pallet adj changer and cmm		
11	BRS	8	pallet adj changer and coordinate		
12	BRS	543	plath.in.		
13	BRS	3	plath.in. and coordinate		
14	BRS	361	pallet adj changer		
15	BRS	1175	coordinate adj measuring adj machine		
16	BRS	136	(coordinate adj measuring adj machine) and machining		
17	BRS	3	((coordinate adj measuring adj machine) and machining) and changer		

	Type	L#	Hits	Search Text
1	BRS	L15	11	(coordinate adj measuring adj machine) and machining and (changer or convey?r)
2	BRS	L22	4	(coordinate adj measuring adj machine) and machining and pallet
3	BRS	L29	1	65247.URPN.
4	BRS	L30	1	
5	BRS	L31	9	4305207.URPN.
6	BRS	L32	1922	herzog.in.

Type	L#	Hits	Search Text
BRS	L39	1	herzog.in. and cmm
,			
BRS	L46	13	herzog.in. and pallet
BRS	L53	4	cmm and pallet and rotat\$3
	BRS	BRS L46	

	Туре	L#	Hits	Search Text
10	BRS	L60	24	4321679.PN. OR 4373804.PN. OR 4394683.PN. OR 4403860.PN. OR 4409718.PN. OR 4453082.PN. OR 4559684.PN. OR 4574199.PN. OR 4576482.PN. OR 4585350.PN. OR 4654949.PN. OR 4667231.PN. OR 4719586.PN. OR 4796200.PN. OR 4851905.PN. OR 4896086.PN. OR 4932828.PN. OR 5005277.PN. OR 5010634.PN. OR 5112131.PN. OR 5148591.PN. OR 5168453.PN. OR 5272805.PN. OR 5381339.PN.

Printed by EAST

UserID: LDejesus

Computer: WS11259

Date: 01/17/2001

Time: 14:31